COMMENTS:

METALS WILL BE REMOVED FROM ORE USING A CONCENTRATING METHOD. USE OF A CONCENTRATOR, ONE FRONT-END LOADER, 2-500 GAL WATER TANKS & A GENERATOR NEEDED. 8" TOPSOIL WILL BE REMOVED & STOCKPILED. SAGE BRUSH WILL BE WINDROWED TO COVER AREA AFTER RECLAIMING & RESEEDING HAS BEEN DONE. NO CHEMICALS WILL BE USED. NO VARIANCES WERE REQUESTED. 96 REPORT SENT IN BY LAMOINE PETERSON. FORMER CONTACT WAS FRANK JORGENSEN, 3015 VANBUREN, OGDEN, UT 84403 (801) 394-1760.